







3. EXTERNAL DIMENSIONS

VIEWING DIRECTION
10:30 O'CLOCK



Remarks:

1. Unmarked tolerance is ± 0.2
2. All materials comply with RoHs
3. ...:critical dimension.